



Monsun[®] 21

DC Box

5LS7910D0






siteco





- 5LS7910D0 + 5LS7 . 2D1T24 . ✓
- 5LS7 . 2D1T44 . ✓
- 5LS7 . 2D1V34 . ✓
- 5LS7 . 2D1V54 . ✓
- 5LS7 . 4D1V44 . ✓

- 5LS7910D0 + 5LS7 . 27... X







4



SIBA
179200.2



5MA21-248845_ae
26.11.2020 / KIN

Siteco GmbH
Georg-Simon-Ohm-Straße 50
83301 Traunreut, Germany
mail: technicalsupport@siteco.de
Phone: +49 8669 / 33-844
www.siteco.com