




# Monsun<sup>®</sup> 21



## DALI Eco Kit Sensorcoupler Kit

5LS792HD1  
5LS792HC1






- 5LS792H . 1+ 5LS7 . 2D1T24B ✓
- 5LS7 . 2D1T44B ✓
- 5LS7 . 2D1V34B ✓
- 5LS7 . 2D1V34C ✓
- 5LS7 . 2D1V54B ✓
- 5LS7 . 2D1V54C ✓
- 5LS724D1V44B ✓
- 5LS724D1V44C ✓




5LS792HD1  
5LS792HC1

2




5LS792HD1  
5LS792HC1



3



4





**i**




1



2



5



**i**

**5LS792HD1**

Die Tageslichtfunktion ist deaktiviert.  
The daylight function is deactivated.



2



5MA21-250880\_ae  
26.11.2020 / KIN

Siteco GmbH  
Georg-Simon-Ohm-Straße 50  
83301 Traunreut, Germany  
mail: [technicalsupport@siteco.de](mailto:technicalsupport@siteco.de)  
Phone: +49 8669 / 33-844  
[www.siteco.com](http://www.siteco.com)